

Storage & Logistics Guidelines

Water Soluble Sewing Thread – PVA Staple Fibre

Ne 40/2 – 2.5 kg Industrial Package

1. Storage Conditions

This product is moisture-sensitive.

Temperature

- Recommended: 15–25°C
- Avoid prolonged exposure above 30°C

Relative Humidity

- Recommended: 50–65% RH
- Avoid high humidity environments

Moisture Exposure

- Keep sealed in original packaging until use
- Do not store near steam lines, washing areas, or open water sources

Sunlight

- Protect from direct sunlight
 - Avoid heat accumulation inside containers or warehouses
-

2. Warehouse Handling

- Store on pallets, not directly on floor
 - Avoid stacking that causes cone deformation
 - Maintain dry storage area
 - Use FIFO (First In, First Out) inventory rotation
-

3. Transport Conditions

Not classified as dangerous goods.

During Transport

- Protect from rain and moisture
- Avoid container condensation
- Avoid exposure to excessive heat
- Do not transport with wet goods

Sea Freight

- Use moisture barrier protection
- Desiccants recommended for long transit routes

Air Freight

- No special classification
 - Standard dry packaging sufficient
-

4. Shelf Life

When stored under recommended conditions:

- 12 months from production date

Extended storage in high humidity may affect performance.

5. Pre-Use Conditioning

If material has been exposed to high humidity:

- Allow to equilibrate in controlled room conditions before use

- Do not rewind or sew immediately after cold-to-warm transfer
-

6. Handling Precautions

- Avoid unnecessary handling in humid environments
 - Avoid placing open cones near active washing or steaming areas
 - Reseal partial packages after use
-

7. Disclaimer

Storage and transport conditions directly influence yarn performance.

Customer is responsible for maintaining controlled storage prior to processing.

8. Contact for Technical Support

For technical queries:

Email: info@durafil-group.com